




Contents


- · ISO/IEC 17025:2017 Requirements
- · Foundations of a Quality Control Programme
- · Internal QC:
 - ✓ Use of Check Standards
 - ✓ Control Charts
 - ✓ Intra-laboratory Comparisons
- External QC:
 - √ PTs/ILCs



Contents

- · ISO/IEC 17025:2017 Requirements
- · Foundations of a Quality Control Programme
- Internal QC:
 - ✓ Use of Check Standards
 - ✓ Control Charts
 - ✓ Intra-laboratory Comparisons
- External QC:
 - ✓ PTs/ILCs









Sub-clause 7.7.1


INTERNATIONAL KNOWLEDGE TRANSFER


Monitoring activities for ensuring validity of results


- a) use of reference materials or quality control materials;
- b) use of alternative instrumentation that has been calibrated to provide traceable results;
- c) functional check(s) of measuring and testing equipment;
- d) use of check or working standards with control charts, where applicable;
- e) intermediate checks on measuring equipment;
- f) replicate tests or calibrations using the same or different methods;
- g) retesting or recalibration of retained items;
- h) correlation of results for different characteristics of an item;
- i) review of reported results;
- j) intralaboratory comparisons;
- k) testing of blind sample(s)

















Contents

- ISO/IEC 17025:2017 Requirements
- Foundations of a Quality Control Programme
- Internal QC:
 - ✓ Use of Check Standards
 - ✓ Control Charts
 - ✓ Intra-laboratory Comparisons
- · External QC:
 - ✓ PTs/ILCs

13





These data can be obtained through:



15



INTERNATIONAL KNOWLEDGE

Evaluation of <u>internally</u> obtained measurement assurance data (cont'd)

Each measurement parameter in the laboratory's scope of activities must be reviewed and analyzed to determine the validity of the measurement process.

- The standards and the measurement process for each parameter must be in a state of statistical control.
- Statistical control means that the variability of the measurement process is known, stable and observed values are adequately close to reference values, within the chosen statistical limits.
- When a process is in statistical control and the reference values are within suitable limits, we can assume that the reported measurement uncertainties are valid.

Evaluation of internally obtained measurement assurance data

Minimizing risks of measurement errors includes all the following laboratory functions:

- a. Training staff and evaluating effectiveness and proficiency
- b. Monitoring the laboratory environment to minimize potential errors or excess variation
- c. Maintaining suitable equipment (including installation, monitoring, approvals, and integrated software)
- d. Selecting and calibrating standards
- e. Ensuring suitable suppliers for materials and calibrations

17

Evaluation of <u>internally</u> obtained measurements INTERNATIONAL assurance data (cont'd) Minimizing risks of measurement errors includes all the following laboratory functions: f. Selecting and validating procedures with evaluation of accuracy/bias and precision g. Ensuring proper care and handling of laboratory standards, equipment, and items submitted for calibration h. Accurately and effectively calculating, evaluating, and reporting measurement uncertainty i. Participating in inter- and intra-laboratory comparisons j. Creating and reviewing calibration certificates to ensure accuracy of measurement results and the effective communication of results k. Controlling data - information management (including software and information technology controls). 18



INTERNATIONAL KNOWLEDGE

Evaluation of <u>externally</u> obtained measurements assurance data

These data can be obtained through:

- a. Evaluation of the calibration history of reference standards, working standards, and check standards
- b. Evaluation of before/after calibrations within a laboratory to compare and evaluate results obtained from an external calibration provider
- c. Review of historical calibration data for items calibrated having demonstrated stability
- d. Comparison of all calibration results and calibration history on control charts for working standards and check standards with results from external calibration sources
- e. Participation in proficiency testing using the same procedures and handling methods used for routine laboratory calibrations
- f. Use of externally obtained data from calibrations, PTs, and ILCs in the assessment of errors and bias in measurement results
- g. Participation in ILCs other than proficiency testing (e.g., for method validation or as a training activity)

19




INTERNATIONAL KNOWLEDGE TRANSFER


Combining Data from Multiple Sources

Measurement results collected over several years may be statistically evaluated with current results being compared to results from previous years.

- Any observed problems or changes in the measurement results are investigated- corrective action taken
- Ongoing monitoring establishes a continuous and comprehensive internal laboratory measurement assurance program

Data from internal measurement assurance programs should be compared to the results of calibration history assessments, interlaboratory comparisons or proficiency tests, and other external sources of data








Contents

- ISO/IEC 17025:2017 Requirements
- · Foundations of a Quality Control Programme
- · Internal QC:
 - ✓ Use of Check Standards
 - ✓ Control Charts
 - ✓ Intra-laboratory Comparisons
- · External QC:
 - ✓ PTs/ILCs

and warning limits

23



The limits are used to establish process uncertainties and to control future measurement performance.

analysed to establish the measurement capability and to set process control



Internal QC- Use of Check Standards- Summary

A check standard must be stable and is normally comparable to the reference standard or to the typical item submitted for calibration, depending on what is being monitored (standards or process).

For lower order calibrations, it should simulate the laboratory's reference or working standards (to the extent feasible).

It should be calibrated using a better procedure than the one being monitored to ensure that the expanded uncertainty is equal to or better than the uncertainty achievable with the process being monitored.

All check standards should be cared for in the same way as reference standards to prevent their damage or deterioration.

Lower order check standards should be recalibrated at regular intervals, according to the laboratory's policy on re-calibration intervals.

25



INTERNATIONAL KNOWLEDGE

Internal QC- Use of Check Standards- Summary


• Control measurements of the check standard are graphed on control charts (\bar{x} and standard deviation charts) for visual examination of process performance and are evaluated against statistical control limits.


 \bar{x} control chart


- Monitors the process with respect to both the standard and the variability
- A central line is drawn, indicating the mean (\bar{x}) of the measured values and control limits are indicated within which the results of measurements are expected to be randomly distributed, based on statistical considerations.
- The control limits consist of the "action" and "warning" limits that represent probabilistic limits for the distribution of results around the central line.


standard deviation chart

monitors the short term precision of the process











Check Standards-Terms used in Control Charts

- bias expresses the difference between the mean value of the measured quantity and the "known" value (the result of the most recent calibration).
- short-term variability- often referred to by the term repeatability and expresses the ability of the device/system to produce under clearly defined measuring conditions the same measurement result.
 - ✓ Repeatability is determined by the standard deviation of a series of repeated measurements.
 - ✓ This standard deviation is a measure of the variability of the measurement process over a short period of time, usually the time necessary to complete one calibration using a particular sequence of measurements called a statistical design. It is called the "within standard deviation" S_w.

31



INTERNATIONAL KNOWLEDGE TRANSFER

Check Standards- Terms used in Control Charts

- long-term variability associated with changes in existing environmental conditions of the laboratory or in the measurement performance.
 - ✓ Often referred to by the term reproducibility and expresses the ability of a process to produce under non-identical measurement conditions the same result.
 - ✓ It is also referred to as a "between" standard deviation, s_b , meaning between calibrations, and is attributed to changes in the calibration process from day-to-day (environmental changes that are not accounted for by modelling, changes in artifact alignment relative to the standard , and other fluctuations that are not reflected in the within standard deviation.



Check Standards- Terms used in Control Charts

• Total standard deviation- includes both the "within" and "between" components of variability

$$s_c = \sqrt{s_w^2 + s_b^2}$$

✓ It reflects both the short-term and long-term random errors that affect the measurement process.

33



Check Standards- Objectives of QC TRANSFER

- QC is used for defining, measuring, analysing, improving, and controlling the measurement process and uncertainty as the calibration is performed through the use of suitable check standards.
- The uncertainty includes effects of the measurement instrument, the operator, the procedure, the standards, and the environment over time.
- Each process is modelled to determine and control:
 - √ 1) the measurement process;
 - ✓ 2) the calibration and check standards; or
 - √ 3) a balance of both the process and the standards.



Check Standards- Objectives of QC TRANSFER

- The objectives will establish the value of the check standard, the check standard measurement procedure, and influence the frequency of control measurements of the check standard.
- Objectives may be:
 - \checkmark 1) Determine the standard deviation of the process (s_p);
 - ✓ 2) Determine the expanded uncertainty, U;
 - \checkmark 3) Measure the value of the calibration standard uncertainty (u_a) .

The model may allow any one objective or a combination of the objectives to be established

35



Check Standards- Methodology

INTERNATIONAL KNOWLEDGE TRANSFER

INTERNATIONAL

- The check standard is selected to evaluate the standard deviation of the process, \mathbf{s}_p , other process uncertainties, $u_{\rm o}$, and possible bias, $u_{\rm d}$ of the process.
- Initial measurements for the check standard should be performed immediately after calibrating the reference or working standards and after the servicing of the measurement instrument.

Symbol	Description
S_c	Control measurement of check standard
S_{cs}	Accepted value of check standard
$oldsymbol{\hat{U}}$	Expanded Uncertainty (of the process)
u_c	Combined standard uncertainty
u_s	Standard uncertainty of the standard
u_o	Standard uncertainty of other factors
u_d	Standard uncertainty of differences
S_{n}	Standard deviation of the process
k	Coverage factor



INTERNATIONAL KNOWLEDGE

Check Standards- Obtain Initial Measurements to Establish Control Charts

- To establish a new control chart, a minimum of 12 or more, independent
 measurements of the check standard should be made, using the same
 standards, equipment, procedure, and under the same conditions that
 will be used to make routine measurements.
- A calibration is defined as the result of replicate measurements as required by the respective SOP (i.e., a complete test consists of the number of runs specified in the SOP).
- No two measurements may be made on the same day.
- The time of day should be varied as would be typical during routine laboratory operations. This is necessary to estimate the long-term standard deviation to the extent feasible. To make statistically valid decisions or calculate uncertainties based on this data, 25 to 30 points are necessary.

37



INTERNATIONAL KNOWLEDGE TRANSFER

Check Standards- Obtain Initial Measurements to Establish Control Charts

- A database is created. This database is the statistical population from which the quality parameters of the measuring process (bias, long and short-term variability) can be identified and quantified.
- b) Using statistical criteria, the compatibility of the latest measurements with the defined quality parameters of the process is examined (process monitoring)
- The quality parameters are adjusted at regular intervals (every 12 measurements) to reflect the most recent state of the measuring processes.



INTERNATIONAL

PTB Check Standards- Obtain Initial Measurements to **Establish Control Charts**

- · Conditions:
- data belong to the statistical distribution (population).
- the distribution is normal
- c) the measuring errors are uncorrelated over time.
- n daily ($n \ge 4$) iterations during m days (n is the same for all the daily repetitions).
- Each point in the database is denoted by X_{ij} (i=1,...m; j=1,...n) The average of the n iterations of the i-day equals:

$$\overline{X}_i = \frac{1}{n} \sum_{i=1}^n X_{i,j}$$

39



INTERNATIONAL **KNOWLEDGE**

Check Standards- Calculations for Construction of Control Charts

- A standard deviation may be calculated for each set of runs according to the appropriate SOP.
- Standard deviation of the *n* repetitions for v=n-1 degrees of freedom (short-term variability of the measuring system):

$$s_i = s_C = \sqrt{\sum_{j=1}^{n} (X_{i,j} - \overline{X}_i)^2 \frac{1}{n-1}}$$

- A pooled standard deviation is then determined for the measurement process.
- Pooled standard deviation: a better estimation of the repeatability of the measurement process and requires the combination of the m daily standard deviations (v=m(n-1)degrees of freedom):

 $s_p = \sqrt{\frac{1}{m} \sum_{i=1}^m s_i^2}$



Check Standards- Calculations Related to Control Charts

 Standard deviation of the m values of the check standard: expresses the long-term variability of the process (v= m-1 degrees of freedom):

$$s_{chkstd} = \sqrt{\frac{1}{m-1} \sum_{i=1}^{m} (\overline{X}_i - \overline{X})^2}$$

General mean value of all the measurements that refer to the check standard

$$\overline{X} = \frac{1}{m} \sum_{i=1}^{m} \overline{X_i}$$

41



INTERNATIONAL KNOWLEDGE

Check Standards- Calculations Related to Control Charts

- Control of the long-term variability of the process: t-test
- Checks whether the measurement difference Δy_{check} from the latest quality control measurement is not essentially different from the overall average of the differences from the previous control measurements.
- A test statistic is computed from the current check standard measurement, the accepted value of the check standard, and the total standard deviation.

$$t = \frac{\left| \Delta y_{check} - \Delta \overline{y}_{check} \right|}{s_{chkstd}}$$
 y: measurand

The calibration process is under statistical control if:

 $t \le$ critical value of t-distribution with n degrees of freedom



INTERNATIONAL KNOWLEDGE

Check Standards- Calculations Related to Control Charts

- Control of the long-term variability of the process: t-test
- Critical value $t_{\alpha/2}(v)$ v Dof: depends on v and on $\alpha/2$, the significance level (probability of mistakenly flagging a check standard measurement as out-of-control).
- Critical values for a two-sided t test with α =0,05:

Degrees of freedom	Critical value	Degrees of freedom	Critical value
1	12,706	14	2,145
2	4,303	15	2,131
3	3,182	19	2,093
4	2,776	24	2,064
5	2,571	29	2,045
6	2,447	34	2,032
7	2,365	39	2,023
8	2,306	44	2,015
9	2,262	49	2,010
10	2,228	50	2,009

43



INTERNATIONAL KNOWLEDGE TRANSFER

Check Standards- Calculations Related to Control Charts

- ullet Control of the short-term variability of the process: F-test
- If the measurement sequence allows for a within standard deviation, the ratio of this within standard deviation to the pooled standard deviation s_p is compared to F(critical value).

$$F = \frac{s_i^2}{s_p^2} \qquad s_i = s_c = \sqrt{\sum_{j=1}^n (X_{i,j} - \overline{X}_i)^2 \frac{1}{n-1}} \quad s_p = \sqrt{\frac{1}{m} \sum_{i=1}^m s_i^2}$$

• The repeatability is under statistical control when:

 $F \le$ critical value of F-distribution with v degrees of freedom for s_i and mv for s_p



INTERNATIONAL KNOWLEDGE

Check Standards- Calculations Related to Control Charts

Control of the short-term variability of the process: F-test

Critical values of F-distribution so that $s_{new}(v) \le s_p(m v)$ for one-sided test with α =0,05:

m∙v	v=1	2	3	4	5	6	7	8	9	10
1	161,45	199,50	215,71	224,58	230,16	233,99	236,77	238,88	240,54	241,88
10	4,965	4,103	3,708	3,478	3,326	3,217	3,135	3,072	3,020	2,978
16	4,494	3,634	3,239	3,007	2,852	2,741	2,657	2,591	2,538	2,494
20	4,351	3,493	3,098	2,866	2,711	2,599	2,514	2,447	2,393	2,348
26	4,225	3,369	2,975	2,743	2,587	2,474	2,388	2,321	2,265	2,220
30	4,171	3,316	2,922	2,690	2,534	2,421	2,334	2,266	2,211	2,165
36	4,113	3,259	2,866	2,634	2,477	2,364	2,277	2,209	2,153	2,106
40	4,085	3,232	2,839	2,606	2,449	2,336	2,249	2,180	2,124	2,077
45	4,057	3,204	2,812	2,579	2,422	2,308	2,221	2,152	2,096	2,049
50	4,034	3,183	2,790	2,557	2,400	2,286	2,199	2,130	2,073	2,026
60	4,001	3,150	2,758	2,525	2,368	2,254	2,167	2,097	2,040	1,993
70	3,978	3,128	2,736	2,503	2,346	2,231	2,143	2,074	2,017	1,969
80	3,960	3,111	2,719	2,486	2,329	2,214	2,126	2,056	1,999	1,951
90	3,947	3,098	2,706	2,473	2,316	2,201	2,113	2,043	1,986	1,938
100	3,936	3,087	2,696	2,463	2,305	2,191	2,103	2,032	1,975	1,927



INTERNATIONAL KNOWLEDGE TRANSFER

Check Standards- Calculations Related to Control Charts

- Shewhart Control Charts: Bias and long-term variability
- Control chart parameters: are evaluated based on a reasonable number of initial measurements and updated as additional measurement data are accumulated.
- A known value is based on a higher-level calibration of the check standard that is preferably independent of the measurement system being monitored.
- The central line is established by the mean of measurements.
- If no higher-level calibration is available, the central line may be used as the known value, but this is not recommended since it will allow no evaluation of measurement accuracy or bias.
- Upper and lower control limits should be fixed, and adjusted after periodic evaluation when/if appropriate.



Check Standards- Calculations Related to Control Charts

Shewhart Control Charts: Bias and long-term variability (\overline{X}_i vs time) Construction of \overline{x} control chart:

• Calculate the mean (central line), \overline{X} , and $s=s_{chkstd}$

$$\overline{X} = \frac{1}{m} \sum_{i=1}^{m} \overline{X_i} \qquad s_{chkstd} = \sqrt{\frac{1}{m-1} \sum_{i=1}^{m} (\overline{X}_i - \overline{X})^2}$$

• Establish the control chart parameters as follows:

Control Chart Parameter	Value
Central Line	\bar{x}
Upper Control/Action Limit (UCL)	$\bar{x} + 3s$
Upper Warning Limit (UWL)	$\bar{x} + 2s$
Lower Warning Limit (LWL)	$\bar{x}-2s$
Lower Control/Action Limit (LCL)	$\bar{x} - 3s$

 $s = s_{chkstd}$




47


INTERNATIONAL KNOWLEDGE TRANSFER


Check Standards- Analyse Data of Control Charts


Standard Deviation Control Charts: Short-term variability (s_i vs time)

- This chart is characterized by the central reference line and the upper control limit.
- This is due to the fact that the deterioration of the short-term variability of the measurement process is expressed only by the increase of the standard deviation of repeated measurements.
- The central/base line is the pooled standard deviation s_n
- Upper control limit: $UCL = s_p \sqrt{F_a(n-1;m(n-1))}$
- α is chosen based on the desired limits (e.g., 0.05 for 95 %).
- *n*-1 represents the degrees of freedom from the replicates.
- m(n-1) represents the DoF corresponding to s_n .











Check Standards- Analyse Data of Control Charts

- Additional guidelines for the evaluation of control charts based on probability statistics should be used to evaluate the presence of drift, shifts, and possible bias. Examples:
 - ✓ Any single point or series of points outside of 3s (keeping in mind the probability that a 3s limit could reasonably expect to allow 3 points out of 1000 to be outside these limits);
 - \checkmark 2 of the last 3 points are above (or below) 2s;
 - \checkmark 4 of the last 5 points are above (or below) 1s;
 - √ 8 consecutive points are on one side of the mean or reference value;
 - √ 6 points in a row are trending up (or down); and
 - ✓ 14 points are alternating up and down (sawtooth pattern) about the mean or reference value.


53





INTERNATIONAL KNOWLEDGE TRANSFER


Check Standards- Analyse Data of Control Charts Nelson Rules

Rule 1	One point is more than 3 standard deviations from the mean.
Rule 2	Nine (or more) points in a row are on the same side of the mean.
Rule 3	Six (or more) points in a row are continually increasing (or decreasing).
Rule 4	Fourteen (or more) points in a row alternate in direction, increasing then decreasing.
Rule 5	Two (or three) out of three points in a row are more than 2 standard deviations from the mean in the same direction.
Rule 6	Four (or five) out of five points in a row are more than 1 standard deviation from the mean in the same direction.
Rule 7	Fifteen points in a row are all within 1 standard deviation of the mean on either side of the mean.
Rule 8	Eight points in a row exist, but none within 1 standard deviation of the mean, and the points are in both directions from the mean.











Check Standards- Analyse Data of Control Charts

Even while the system is in an apparent state of control, incipient troubles may be indicated when the control data show **short or long term trends**, **shifts**, **or runs**.(Use *F* and *t*-tests to estimate their significance)

If the values plotted on the standard deviation chart fall outside of the control limits, a decrease in precision is indicated. Problems with the standards or process will need to be investigated

If the plotted value of \bar{x} lies outside of the control limits and the corresponding value on the standard deviation chart is within the control limits, a source of **systematic error** is suspected.


59




INTERNATIONAL KNOWLEDGE TRANSFER

Check Standards- Analyse Data of Control Charts

- Demonstration of "in control" indicates that the calibration process is consistent with the past experience of the laboratory. There is no reason to believe that excessive changes in precision have occurred.
- To the extent appropriate, the indicated measurement precision of the calibration of the measured type of standards may be extended to the calibration of other standards of similar type, capacity and design.







INTERNATIONAL KNOWLEDGE

Check Standards- Analyse Reference Values ER

- The Normalized Error, E_n , may be used to compare the mean value of the check standard, S_c to the calibrated reference value, S_{cs} (once adequate metrological traceability for the reference value is ensured).
- Expanded uncertainty of the reference value from the calibration certificate.
 - Uncertainty of the mean value of the check standard :

$$u_c = \sqrt{\frac{s_p^2}{n} + u_s^2 + u_0^2} \qquad \qquad U_{\overline{S_c}} = k \times u_c$$

- s_p : standard deviation of the process from the control chart,
- *n* the number of relevant data points;
- u_s :standard uncertainty of the standard
- u_o : any other critical components to be considered.

63



INTERNATIONAL KNOWLEDGE

Check Standards- Analyse Reference ValuesER

$$E_n = \frac{|\overline{S_c} - S_{cs}|}{\sqrt{U_{\overline{S_c}}^2 + U_{S_{CS}}^2}}$$

- $|E_n| \le 1$ to pass
- If $|E_n| > 1$, corrective action is required.



Check Standards-Improve the Process

During analysis of the measurement process or the reference and check standards, opportunities for corrective action and improvement action may be identified.

Control charts or values that do not have normal distributions or which have significant differences between observed measurement results and reference values are cause for action of some type.

During review of the charts, the first step is to identify the source/cause of the concern, and the associated actions will generally follow.

65



INTERNATIONAL KNOWLEDGE

Check Standards-Improve the ProcessANSFER

• Examples:

Assignable Cause – Source of Problem	Example Action Item
Standard deviation has increased after new staff member is hired	Staff might need training, instruction, or oversight; uncertainties may need to be increased
Standard deviation has increased over the past year	Devices may need service; uncertainties may need to be increased
Standard deviation has gotten smaller over the past few months (due to staff training or devices service)	,
1 1 1	For example, replace standards, update values of standards, validate software, contact calibration provider. Evaluate whether the shift corresponds in direction and magnitude to changes in the
Standard values are demonstrating a drift over time. Possibilities may be that standards were not equilibrated long enough before being placed into service; standard or check standard type and 6 design might be inherently unstable.	Allow standards to equilibrate longer; replace unstable standards or check standards.



Check Standards- Updating Control Chart Parameters

- Update control chart parameters when:
 - ✓ a significant amount of additional data is available, or
 - ✓ the previously determined parameters are no longer relevant due to changes in the system.

67



INTERNATIONAL KNOWLEDGE TRANSFER

Check Standards- Updating Control Chart Parameters

IF:	THEN:		
The tests fail and results are significantly different	Determine the reason for the difference, if possible, and decide whether corrective action is required.		
Data do not agree within statistical limits	Establish new parameters and limits using the most recent data and note the reasons for not using previous data or correct the causes of variation.		
Portions of the process or standard variations pass	Be sure to note the degrees of freedom to support uncertainty analyses and coverage factors.		
No significant differences between the data sets are found	Pool all data and calculate new control chart parameters based on all existing data.		



Check Standards- Control the Process

- How frequently should the check standard be measured and plotted?
 - ✓ Sufficient frequency to minimize the risk of loss of data during the period from last-known-in to first-known-out of control condition.
- Good practice: measure the check standard at least once during each period when a set of calibration measurements is made.
- For critical calibrations or those of highest accuracy, it is desirable to alternate measurements of calibration items and check standards.
- For real-time evaluation it is preferable to incorporate the check standard in the calibration design (SOP).

69



INTERNATIONAL KNOWLEDGE TRANSFER

Check Standards- Control the Process

- Whenever there has been a long period of inactivity, it is good practice to make a series of measurements of the check standard and to plot the results on a control chart to demonstrate attainment of statistical control prior to resuming measurements with that specific calibration system.
- Check standard measurements should be plotted in control charts as close to real time as feasible to effectively monitor the measurement process and to prevent the possible release of questionable data that may result in the recall of laboratory work.

PB Check Standards- Checklist for Creation or Evaluation of Control Charts			
Control Charts cover entire scope (are available for each measurement parameter).			
Control charts have titles (or otherwise include)			
Laboratory name or other identifying information			
SOP(s) used to generate measurement result			
Equipment			
Standard Identification, Check standard Identification			
Nominal value			
Dates/chronology/time periods if not used on the x axis			
Legends if multiple series and extra information are plotted (to avoid confusion)			
Control charts have x and y axis with labels and			
All measurement values have units of measure associated with them			
Control charts have			
Mean value (and units)			
Standard deviation (and units)			
Degrees of freedom or number of points noted (if not obvious or if small number)			
Alternative summaries of this information and suitable references (e.g., tables)			
Printed summary reports of control data with the charts			
Reference values and source and bias if appropriate/available			

PIB

71

INTERNATIONAL KNOWLEDGE

Check Standards- Checklist for Creation or Evaluation of Control Charts


Control charts have limits that are based on

St	tatistical controls of:		
	Warning limits (i.e., two standard deviations) and		
	Action/control limits (i.e., three standard deviations)		
Oi	r, specification limits (e.g., tolerances or smaller ratios of tolerances)		
	Good Items (on chart or in spreadsheet or database table summaries). Control charts have (when applicable and meaningful if not otherwise noted, e.g., in a table)		
To	plerances: when applicable		
Uı	ncertainties: for the reference value, check standard, and the process output		
1	quipment information: device readability, configuration (stability ettings/timing)		
St	tandard information: calibration date and interval information		
Re	esponsible staff: need on chart or in database		
St	tatus of control: in control, out of control with latest date of review		
	istory: previous limits and history of the chart/data with F-test and/or t-test esults		



Check Standards- Transfer of Statistics

- The estimate of the standard deviation of the process, s_p , used to establish the control limits may be used to calculate confidence intervals for all related measurements made while the system is in control.
- The value of the item being calibrated is said to be within the limits if the combined mean of the measurements on the calibration item and the expanded uncertainty are within limits.





Check Standards- EWMA Control Charts

- Exponentially Weighted Moving Average (EWMA) is a statistic for monitoring the process that averages the data in a way that gives less and less weight to data as they are further removed in time.
- The decision depends on the EWMA statistic, which is an exponentially weighted average of all prior data, including the most recent measurement.
- By the choice of weighting factor, λ , the EWMA control procedure can be made sensitive to a small or gradual drift in the process, whereas the Shewhart control procedure can only react when the last data point is outside a control limit.

Lucas, J. M. and Saccucci, M. S. (1990). "Exponentially weighted moving average control schemes: Properties and enhancements", *Technometrics* 32, 1-29.

75





INTERNATIONAL KNOWLEDGE TRANSFER

Check Standards- EWMA Control Charts

- The EWMA control chart is characterized by a central reference line that results from the average of all values in the control template database and from two bounding lines, UCL and LCL:
- $EWMA_t = \lambda Y_t + (1 \lambda)EWMA_{t-1}$ for $t = 1, 2 \dots, n$
- $s_{EWMA}^2 = \frac{\lambda}{2-\lambda} s^2$
- $UCL = EWMA_0 + ks_{EWMA}$
- $LCL = EWMA_0 ks_{EWMA}$
- *k* usually =3

- *EWMA*₀ is the mean of historical data (target)
- Y_t is the observation at time t
- n is the number of observations to be monitored including EWMA₀
- 0 < λ ≤ 1 is a constant that determines the depth of memory of the EWMA
- s is standard deviation calculated from the historical data







Internal QC- Intra-laboratory Comparisons

- An intra-laboratory comparison is conducted when:
 - ✓ Several technicians within an organization perform calibrations on the same or similar artifact, using the same method, under specified, controlled conditions.
 - ✓ The same artifact is measured by using different methods or different calibration systems.
- The data resulting from these activities shall be analysed for statistical validity


79




INTERNATIONAL KNOWLEDGE TRANSFER

Contents

- ISO/IEC 17025:2017 Requirements
- · Foundations of a Quality Control Programme
- · Internal QC:
 - ✓ Use of Check Standards
 - ✓ Control Charts
 - ✓ Intra-laboratory Comparisons
- · External QC:
 - √ PTs/ILCs







External QC- Participation in PTs/ILCs- Assessment of Results Evaluation of PT/ILC results for calibration laboratories:

• Bias (Difference): $x_{lab} - X_{ref}$

This value is not used as a pass/fail statistic, but is used in the initial assessment of data by the PT provider to review the overall data for obvious blunders and outliers.

The laboratory may use this value as a part of its follow-up assessments of laboratory bias, accuracy goals, and plans for recalibration limits. (For precision calibrations, a laboratory might want to set recalibration goals such that whenever the bias/offset exceeds some ratio of its reported uncertainty, a recalibration or interim assessment of metrological traceability is conducted).

8:




INTERNATIONAL KNOWLEDGE TRANSFER

External QC- Participation in PTs/ILCs- Assessment of Results

Evaluation of PT/ILC results for calibration laboratories:

• Normalized Error
$$E_n$$
: $E_n = \left| \frac{x_{lab} - x_{ref}}{\sqrt{U_{lab}^2 \pm U_{ref}^2}} \right| < 1$ to pass When + ? When - ?





External QC- Participation in PTs/ILCs- Assessment of Results

- · Lab A:
 - ✓ The value submitted is outside the uncertainty of the reference value
 - ✓ Its uncertainty overlaps the reference value.
 - ✓ Visually, there is a good amount of overlap of the uncertainty bars.
 - ✓ E_n (=0.689) < 1 Pass.
- · Interpretation:

An E_n value of 0.689 might still justify further assessment of the laboratory accuracy by determining if the Bias (Difference) that is shown has been consistent in previous PTs or is observed in a laboratory control chart. Further evaluation would depend on the applicable tolerances for the application and the desired level of accuracy needed by the laboratory

1.25 En = 0.689




INTERNATIONAL KNOWLEDGE

En = 1.115

External QC- Participation in PTs/ILCs- Assessment of Results

- Lab B:
 - ✓ The value submitted is identical to the value from lab A, thus the Bias (Difference) is also identical.
 - $\checkmark U_B < U_A$ and $U_B < U_{ref}$
 - \checkmark While the uncertainties still overlap slightly, $U_{\it B}$ does not overlap the reference value, $U_{\it ref}$ does not overlap the submitted lab B value



 \checkmark E_n (=1.115) > 1 Fail.

Interpretation:

The Bias (Difference) for both labs A and B are identical, but U_B does not support this level of bias. Either the uncertainty is too small if all other laboratories performed the same procedure and submitted uncertainties comparable to Labs A and C (likely) or the laboratory needs to identify the root cause of this failure (e.g., a systematic error of some type or the need for recalibration of standards to bring values closer to the reference value).

87




INTERNATIONAL KNOWLEDGE TRANSFER

External QC- Participation in PTs/ILCs- Assessment of Results

- · Lab C:
 - ✓ The value submitted is not inside reference value uncertainty.
 - $\checkmark U_C = U_A$
 - ✓ There is very minor overlap of uncertainty values, but the overlap is not enough.





Interpretation:

Some laboratories working with larger tolerances might suggest that the offset does not matter and the failure is not significant, which is counter to the purpose of PTs. If the tolerances are significantly larger than the offset shown, a larger uncertainty to cover the gap and pass the E_n assessment is likely warranted.



External QC- Participation in PTs/ILCs- Follow-up Actions

- Pass/fail status of each standard evaluated in the PT is not the only thing a laboratory should consider when participating in a PT.
- Recommendation: Prepare a thorough follow up assessment that creates an Executive Summary that can be used in a Management Review as well as guiding the laboratory in performing a thorough assessment of the report, even when all indicators were successful.

89





INTERNATIONAL KNOWLEDGE TRANSFER

External QC- Participation in PTs/ILCs- Follow-up Actions

• Example of Executive Summary Report:

Assessment	Results and Evidence
1. Executive Summary	
2. PT Failures	
3. Analysis and Action Plan	
4. Deadlines	
5. Uncertainties (7.6., 7.8.6).	
6. Uncertainty versus Applicable	
Tolerances (7.8.6).	
7. Offset/Bias Assessment (7.7)	
8. Records (7.5, 7.8, 8.4).	
9. Non-Measurement Result	
Observations or Failures	







INTERNATIONAL KNOWLEDGE

External QC- Participation in PTs/ILCs- Follow-up Actions

• Example of Executive Summary Report:

5. Uncertainties (7.6., 7.8.6). Questions to consider include:

How did the reported uncertainty compare to other participating laboratory values?

Was the correct k factor used?

If the laboratory (or laboratory participant(s)) uncertainty value(s) were at the high end of the uncertainties, explain why. Could a better procedure or instrument have been used?

If at the low end, was the value calculated correctly? Why is it smaller than the values reported by other laboratories?

Explain if all appropriate uncertainty components were included (or why they were not included). Describe the planned measurement process and/or actual procedure used for the PT (higher/lower level procedure).

93



INTERNATIONAL KNOWLEDGE

External QC- Participation in PTs/ILCs- Follow-up Actions

Example of Executive Summary Report:

6. Uncertainty versus Applicable Tolerances (7.8.6). Questions to consider include:

Was a precision test conducted as a part of the analysis? If yes, explain why there any ranges with unacceptable results. If no, conduct the precision analysis now.

The calculation evaluates the reported uncertainty(expanded at k=2) against the tolerances required for the equipment with any uncertainty to tolerance ratios considered. Was the uncertainty reported acceptable/appropriate for the level of work? Could the uncertainty be improved with different equipment or procedures?



External QC- Participation in PTs/ILCs- Follow-up Actions

• Example of Executive Summary Report:

7. Offset/Bias Assessment (7.7).:

Was bias observed in the PT also observed in other types of measurement assurance charts in the laboratory? Describe or summarize the bias and offset of the laboratory PT.

8. Records (7.5, 7.8, 8.4):

Describe the assessment in place to track PT data over time within the laboratory and evaluate the data against previous results and other data. Ensure that the final results were entered in laboratory PT log and identify the summary data that will be included in the Management Review (8.9).

9. Non-Measurement Result Observations or Failures:

Describe any additional feedback related to the PT planning, scheduling, evaluation (e.g., delays) or reporting results (e.g., calibration certificate review, 7.8) that were provided as a part of this PT.

95



INTERNATIONAL KNOWLEDGE

External QC- Participation in PTs/ILCs- Follow-up Actions

Example of Executive Summary Report:

7. Offset/Bias Assessment (7.7). Questions to consider include:

Was the $E_n > 1$? If $E_n > 1$, a measurement bias was indicated. If a bias was present, are there any overriding reasons for it?

An investigation generally needs to be conducted looking for common errors and problems: e.g., incorrect values for the standard used, errors in software used for calculations, deviations from SOPs, need for calibration of standards.

Conduct an investigation of bias (even if values passed the E_n analyses) against internal calibrations, control charts, previous PT results or recent calibrations to find out if there is correlation of the ILC data with internal laboratory data.

Was the bias for all laboratory participants similar? If not, describe why.



Conclusions

- The major advantage of a successful system of Quality Control is the ability to evaluate the reference standards and the measurement process over time, providing ongoing assurance regarding accuracy and traceability of the reference standards for both the laboratory and its customers.
- When a process is in statistical control and the reference values are within suitable limits, we can assume that the reported measurement uncertainties are valid.
- Ongoing evaluation of the measurement process provides the laboratory with data that can be used to establish or adjust calibration intervals for reference standards.
- The measurement assurance program is also critical for defining and reporting realistic uncertainties.

97



INTERNATIONAL KNOWLEDGE TRANSFER

References

- ISO/IEC 17025:2017: General requirements for the competence of testing and calibration laboratories.
- JCGM 100:2008 "Guide to the expression of uncertainty in measurement"
- M. Grabe, "Principles of Metrological Statistics", Metrologia 23, (1986/1987), 213.
- K.Weise and W. Woeger, "A Bayesian Theory of Measurement Uncertainty", Meas. Sci. Tech. 3, (1992), 11.
- C. Eisenhart, "Realistic Evaluation of the Precision and Accuracy of Instrument Calibration Systems", NBS Special Publication 300, vol. I, H.H. Ku editor, Washington DC 1969, pp. 21-48.



References

- A.J. Duncan, "Quality Control and Industrial Statistics", 5th ed., Irwin, Homewood, IL, 1986.
- Bucher, J.L., "Quality Calibration Handbook—Developing and Managing a Calibration Program", ISA Publication, ASQ Quality Press, 2007.
- J.K. Taylor and H.V. Oppermann, "Handbook for the Quality Assurance of Metrological Measurements", NBS Handbook 145, Gaithersburg, 1986.
- NIST/SEMATECH e-Handbook of Statistical Methods, http://www.itl.nist.gov/div898/handbook/, January 19, 2019

